### MARYLAND HISTORICAL TRUST



1	NAME	200			2 AMA A	E	
	HISTORIC 1531	Myrtle Avenue			MIHP No.	B-5197	
_	AND/OR COMMON						
2	LOCATION	ı					
	STREET & NUMBER	1500 Block Myrtle	Avenue				
	CITY, TOWN		VICINITY OF	С	ONGRESSIONAL DISTR	ICT	
_	STATE VICINITY OF			COUNTY			
3	CLASSIFIC	ATION				я.	
	CATEGORY	OWNERSHIP	STATUS		PRES	ENTUSE	
	_DISTRICT	PUBLIC	_OCCUPIED		AGRICULTURE	_MUSEUM	
	_BUILDING(S)	PRIVATE	-UNOCCUPIED		COMMERCIAL	PARK	
	_STRUCTURE	_вотн	_WORK IN PROGRESS		EDUCATIONAL	_PRIVATE RESIDENCE	
	_SITE	PUBLIC ACQUISITION	ACCESSIBLE		ENTERTAINMENT	RELIGIOUS	
	OBJECT	_IN PROCESS	_YES: RESTRICTED		GOVERNMENT	_SCIENTIFIC	
		BEING CONSIDERED	_YES: UNRESTRICTED		_INDUSTRIAL	_TRANSPORTATION	
	5	أستعمل بنيء وبد	_NO	L.V	MILITARY	_OTHER	
	NAME				Telephone #:		
	STREET & NUMBER						
	CITY. TOWN		VICINITY OF		STATE , Z	ip code	
į	LOCATION	OF LEGAL DESCR					
-			= 5 962	Libe	500 M.S.S.		
	COURTHOUSE. REGISTRY OF DEEDS, E	TC.		Foli	o #:		
_	STREET & NUMBER	cords Office Room 60	)1				
	CITY. TOWN	ltimore City Courtho	use		STATE		
		timoro, Maryland 3	21202				
Ī		TATION IN EXIST					
	TITLE 3						
_	DATE	ty of Baltimore Neig	hborhood Survey				
_	DEPOSITORY FOR	78	FEDERAL _	_STATE _	COUNTY _LOCAL		
_		mission for Histori	c and Architectu	eral P	reservation		
		timore, Maryland 2			STATE		



# 7 DESCRIPTION

#### CONDITION

\_EXCELLENT

\_DETERIORATED

\_\_GOOD

\_\_RUINS

CHECK ONE

\_\_UNALTERED

CHECK ONE

\_ORIGINAL SITE

MOVED DATE\_\_\_\_

### DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The rowhouse is two stories high and three bay wide with common bond building and foundation walls and a flat roof. Fenestration is proportional and symmetrical. The left bay of the foundation wall is punctuated by a flat aperture for a door. It is capped with a brick lintel and reached by way of four concrete steps that descend to meet its concrete stoop. All the apertures in the building are flat and boarded over. The center bay of the foundation wall is punctuated by an aperture with a accompanying brick sill. The center and left bays of the first story facade are punctuated by aperture, of the same size and are accompanied by wood sills and splayed brick lintels. The remaining bay is punctuated by an aperture for a door, which would have rested on a stone stoop. The steps leading to the door have been removed. The aperture is accompanied by a brick lintel. Each bay of the second story facade is punctuated by an identically sized aperture accompanied by wood sills and splayed brick lintels. A wood frieze and wood cornice carrying dentals and supported brackets surmount the building facade.

## 8 SIGNIFICANCE


PERIOD	AF		~		
_PREHISTORIC	_ARCHEOLOGY-PREHISTORIC	_COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	_RELIGION	_
_1400-1499	_ARCHEOLOGY-HISTORIC	CONSERVATION	_LAW	_SCIENCE	
_1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE	
_1600-1699	_ARCHITECTURE	EDUCATION	MILITARY	_SOCIAL HUMANITARIAN	
_1700-1799	ART	ENGINEERING	MUSIC	_THEATER	
_1800-1899	COMMERCE	EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION	
_1900-	COMMUNICATIONS	_INDUSTRY	POLITICS/GOVERNMENT	_OTHER (SPECIFY)	
		_INVENTION			

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The 1500 block of Myrtle Avenue included houses of a variety of styles and sizes. Some were very ornately decorated, for example the window hoods of #1533. Others were simple and typical of housing in the area (#1531). The differing treatments of cornices, door and window lintels, and window sills provided a diversity along the streetscape. This block was razed c.1976.



B-5197 1531 Mrytle Avenue Block 0359 Lot 040 **Baltimore City** 

### **Demolished**

